PROJECT NAME: Raven Sanitary Forcemain			No.: SANI-IMPRV-0018
ASSET TYPE: Sani	SUBTYPE: Main	LOCATION MAP	
WORK TYPE: Replacement		SANI-IMPRV-0018	4851 N
LOCATION: Foreshore			5080
From: 47 Ave NE		5001	4801 4800
To: Northern Edge of 1031, 47 Ave NE		4	4791 A791
ANTICIPATED PROJECT YEAR: 2019		_	
PROJECT COST (Attach est.): \$78,000			1121
DESIGN: FILE NO.:			0000
ANTICIPATED YEARLY O&M: \$0		1031	1061
COMMENTS:			gr.page 1000
Look at option to install in	easement along Railway R/W	1033	1050 TOSO
PROJECT DESCRIPTION : Reaccessible location within		230m of 150mm AV forcemain w	ith 150mm PVC. Replace in
PROJECT JUSTIFICATION: section.	Collection of sewer gases caus	se corrosion to AC pipe. Utilities	raised concerns regarding this
CONDITION: ?	RISK: 1-High	CAPACITY: 5-Excellent	RISK: 3-Medium
OVERALL CONDITION/RISK SCORE:			
CURRENT STATUS: What is currently being done to maintain? Associated annual cost inc. O&M? N/A			
OPTIONS: What other options are there to mitigating the risk? Associated Cost inc. O&M? Repair of future breaks; however location is inaccessible during a large poriton of the year.			